## red-y for gasflow

# Compression fittings with 50µ filter



Fitting with filter (marked with two green dots)



Fitting without filter

The fittings are delivered <u>in pairs</u> and must be mounted as follows: with filter at the inlet and without filter at the outlet.

#### Versions

| Article  | Type/Connections | Materials            |
|----------|------------------|----------------------|
| 328-1001 | G ¼″ to 6mm      | Stainless steel, FKM |
| 328-1002 | G ¼″ to ¼″       | Stainless steel, FKM |
| 328-1003 | G ¼″ to 12mm     | Stainless steel. FKM |
| 328-1004 | G ¼″ to ½″       | Stainless steel, FKM |
|          |                  |                      |

#### **Replacement filter**

| Article  | Description |  |  |
|----------|-------------|--|--|
| 328-1401 | Filter disc |  |  |

**Quantity** 5 units

## Pressure loss (air)

| Flow      | Pressure loss G ¼" |  |  |
|-----------|--------------------|--|--|
| 5 ln/min  | 2.2 mbar           |  |  |
| 20 In/min | 25 mbar            |  |  |
| 40 In/min | 85 mbar            |  |  |
| 60 ln/min | 180mbar            |  |  |

#### **Dimensions (mm)**


| Туре           | Α    | в    | Wrench size |
|----------------|------|------|-------------|
| G ¼″ to 6mm    | 32   | 20   | 19          |
| G ¼″ to ¼″     | 32   | 20   | 19          |
| G ¼″ to 12mm   | 33.5 | 21.5 | 27          |
| G 1⁄4″ to 1⁄2″ | 33.5 | 21.5 | 27          |
|                |      |      |             |

## Mounting


The fitting with filter must be mounted at the inlet (in the direction of the flow).

Do not injure the seals (O-rings) during mounting.

Please do not use liquid sealants or Teflon tape for sealing the threads.



Mounting of the fittings



**Dimensions (without connecting nut)** A = Overall length B = Outside length after mounting



Vögtlin Instruments AG – flow technology Langenhagstrasse 1 | 4147 Aesch (Switzerland) Phone +41 (0)61 756 63 00 | Fax +41 (0)61 756 63 01 www.voegtlin.com | info@voegtlin.com

